


Stripping of Wood Windows

An orbital sander with coarse paper can quickly remove thin paint, then sand to a smooth finish using fine paper.

When disturbing paint that may contain lead, always connect power tools to a HEPA vac to gather and contain most of the dust.

The infrared heat gun softens paint and glazing putty without burning wood. It creates a minimum of fumes, but user must still wear a respirator with carbon filters to be protected from lead paint fumes.

The planer removes paint from flat surfaces in a couple of strokes. The depth of cut can be easily adjusted.



Even when using a HEPA vac, always do this work in containment and wear at least an N 100, R100, or P100 respirator.

At the end of the operation. clean up area with a HEPA vac. then wet mop.

The HEPA vac, sander, and planer shown are made by Festo Co. III